

VOLVO L150E

Description

Volvo L150E, Engine Volvo D9ALBE2, 199 kW, EPA, Erops cabin, 26.5 R25 tyres, GP bucket with teeth, Width of the bucket 3.00m, Complete steering wheel, Autoshift, Backup alarm, Beacon, AM/FM radio, Hours checked with diagnostic computer, In very good and clean condition.



| | |
|----------------------|------------|
| Year | 2004 |
| Hours | 18846 |
| Weight | 26100 |
| Serial number | L150EV8012 |
| Reference | 181723 |

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

| | |
|--------------|----------------|
| Engine | Volvo D9ALBE2, |
| Engine power | 199 kW, |

GENERAL APPEARANCE

| | |
|--------------------------------|-------|
| Stamped serial number checked | Yes |
| Serial number plate checked | Yes |
| Paint | ★★★★☆ |
| Decals | ★★★★☆ |
| Bonnet | ★★★★☆ |
| Engine cover doors | ★★★★☆ |
| Chassis | ★★★★☆ |
| Steps/ladders | ★★★★☆ |
| Grab irons | ★★★★☆ |
| Cabin | ★★★★☆ |
| Pre-cleaner bowl | ★★★★☆ |
| Toolbox | ★★★★☆ |
| All greasing points lubricated | No |
| Central greasing working | No |

ENGINE DETAILS AND CONDITION

| | |
|--------------------------|-------|
| Engine number | 14252 |
| EPA sticker available | Yes |
| Air cleaner | Clean |
| Anti-freeze level °C | -28 |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★☆ |
| Muffler | ★★★★☆ |
| Exhaust stack | ★★★★☆ |
| Engine supports | ★★★★☆ |
| Hoses | ★★★★☆ |
| Good cold start | Yes |

| | |
|-----------------------------|--------|
| Engine power | ★★★★★ |
| Blow by | ★★★★★ |
| Knocking | No |
| Compression in the radiator | No |
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |
| Belts and pulleys | ★★★★★ |
| Fan | ★★★★★ |
| Radiator | ★★★★★ |

OPERATOR STATION

| | |
|-------------------|-----------------------|
| Hourmeter | Working |
| Gauges | Working |
| Switches | ★★★★★ |
| Display | ★★★★★ |
| Warning | No warnings available |
| Mirrors | Not broken |
| Cabin glass | Not broken |
| Windshield wipers | Working |
| Interior lights | Working |
| Cabin floor | ★★★★★ |
| Interior roof | ★★★★★ |
| Seat | ★★★★★ |

BUCKET

| | |
|---------------------------------|-------|
| Overall condition of the bucket | ★★★★★ |
| Bottom | ★★★★★ |
| Sides | ★★★★★ |
| Cutting edge | ★★★★★ |
| Teeth | ★★★★★ |

FRAME

| | |
|-------------------------|-------|
| Play articulation point | ★★★★★ |
| Play loading frame | ★★★★★ |
| Play bucket pins | ★★★★★ |
| Crack or welds | No |

HYDRAULICS

| | |
|------------------------------------|-----------|
| Hydraulic oil level ok | Yes |
| Hydraulic lines and fittings | ★★★★★ |
| Hydraulic tank/sight glass and cap | ★★★★★ |
| Hydraulic valves leaking | Not major |
| Noise hydraulic pump normal | Yes |
| Operating condition hydraulics | ★★★★★ |

BRAKE

| | |
|-------------------------|-------|
| Brakelines | ★★★★★ |
| Service brake operation | ★★★★★ |
| Parking brake operation | ★★★★★ |
| Compressor | ★★★★★ |

DRIVE TRAIN/TRANSMISSION

| | |
|---|-----|
| Transmission fully operational in all gears forward and reverse | Yes |
| Transmission oil level ok | Yes |
| Transmission noisy | No |
| Oil level front axle ok | Yes |
| Oil level rear axle ok | Yes |
| Drivetrain leaks | No |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|--------------------------------|-------|
| Alternator functioning | Yes |
| Wiring | ★★★★★ |
| Batteries | ★★★★★ |
| Starter | ★★★★★ |
| Cabin lights working | Yes |
| Additional work lights working | Yes |

SAFETY ITEMS

| | |
|--------------|-----------|
| Backup alarm | Working |
| Seat belt | Available |
| Horn | Working |
| Beacon | Working |

TYRES

FRONT LEFT

Percentage life remaining 20%

REAR LEFT

Percentage life remaining 20%

REAR RIGHT

Percentage life remaining 40%

FRONT RIGHT

Percentage life remaining 30%

