

# Cat Electronic Technician 2019C v1.0

## Product Status Report

20-1-2021 11:10

### Product Status Report

Parameter	Value
Product ID	EDW00228
Equipment ID	NOT PROGRAMMED
Comments	

### Implement 972M (EDW00228)

Parameter	Value
Product ID	EDW00228
Equipment ID	
ECM Part Number	3656773-04
ECM Serial Number	22746491VD
Software Group Part Number	5910648-00
Software Group Release Date	DEC2019
Software Group Description	972 Implement

### Logged Diagnostic Codes [Diagnostic Clock = 9504 hours] - Implement 972M (EDW00228)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

### Transmission 972M (LCN00387)

Parameter	Value
Product ID	EDW00228
Equipment ID	
Transmission Serial Number	LCN00387
ECM Part Number	3656790-04
ECM Serial Number	21646102QQ
Software Group Part Number	5910605-00
Software Group Release Date	DEC2019
Software Group Description	972M Transmission
Active Diagnostic Codes Present	No

### Logged Diagnostic Codes [Diagnostic Clock = 9504 hours] - Transmission 972M (LCN00387)

Code	Description	Occ.	First	Last
248- 9	Cat Data Link not communicating	1	9504	9504
596- 9	Implement Control : Abnormal Update Rate	1	9504	9504
596-12	Wrong Response from Implement ECM	2	9504	9504

2199- 3	Secondary Steering Request Signal Line : Voltage Above Normal	1	9504	9504
---------	---	---	------	------

### Diesel Exhaust Fluid Controller #1

Parameter	Value
Aftertreatment #1 DEF Dosing System Serial Number	PET007258T
Application Software Part Number	5937033-00

### C9 972 (SYE02292)

Parameter	Value
Equipment ID	NOT PROGRAMMED
Engine Serial Number	SYE02292
ECM Part Number	4176020-00
ECM Serial Number	18146119VJ
Software Group Part Number	5903670-00
Software Group Release Date	APR20
Software Group Description	MWL 966/972 XE
Operator Inducement Regulation Configuration	Worldwide

### Logged Diagnostic Codes [Diagnostic Clock = 9504 hours] - C9 972 (SYE02292)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

### Indication Display

Parameter	Value
ECM Part Number	3743612-02
ECM Serial Number	22348002DT
Software Group Part Number	5523605-00
Software Group Release Date	NOV2017
Software Group Description	Indication Display

### VIMS Main Module (EDW00228)

Parameter	Value
Machine Serial Number	EDW00228
Product ID	EDW00228
Equipment ID	
ECM Part Number	3402413-05
ECM Serial Number	19549048RN
Software Group Part Number	4761900-00
Software Group Release Date	FEB15
Software Group Description	PLGSM 2014B PROD 1.0
Application Software Part Number	Unavailable
Telematic Device Software Group Part Number	5809705-00
Telematic Device Software Group Release Date	MAR2019
Telematic Device Software Group Description	PROD-4.3.11

Logged Diagnostic Codes [Diagnostic Clock = 9504 hours] - VIMS Main Module (EDW00228)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Input/Output Module

Parameter	Value
ECM Part Number	2995744-05
ECM Serial Number	1824B085HZ
Software Group Part Number	4805894-00
Software Group Release Date	SEP2015
Software Group Description	Relay Driver Module

Graphical Display (EDW00228)

Parameter	Value
ECM Part Number	3732281-04
ECM Serial Number	1994G003UM
Software Group Part Number	5328941-00
Software Group Release Date	MAY2017
Software Group Description	MWL_20.459_May.01.2017

Logged Diagnostic Codes - Graphical Display (EDW00228)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Engine #1 Aftertreatment Controller

Parameter	Value
Equipment ID	NOT PROGRAMMED
Engine Serial Number	SYE02292
ECM Part Number	3943902-02
ECM Serial Number	24547138QU
Software Group Part Number	5903671-00
Software Group Release Date	APR20
Software Group Description	AFT_T4F_C9.3_HWA_A5E2V1

Logged Diagnostic Codes [Diagnostic Clock = 9504 hours] - Engine #1 Aftertreatment Controller

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				