

Cat Electronic Technician 2021C v1.0

Product Status Report

30-6-2022 09:53

Product Status Report

Parameter	Value
Product ID	T4P00266
Equipment ID	735B
Comments	

Trans/Chassis 735 (K2S00464)

Parameter	Value
Product ID	T4P00266
Equipment ID	735B
ECM Part Number	3045687-02
ECM Serial Number	09016563MS
Software Group Part Number	4781152-00
Software Group Release Date	JUN2015
Software Group Description	735B

Logged Diagnostic Codes [Diagnostic Clock = 8954:19:55 hours] - Trans/Chassis 735 (K2S00464)

Code	Description	Occ.	First	Last
96- 3	Fuel Level Sensor : Voltage Above Normal	1	8954:19:30	8954:19:30

Chassis 735 (T4P00266)

Parameter	Value
Product ID	T4P00266
Equipment ID	735B
ECM Part Number	3045687-02
ECM Serial Number	09416343MS
Software Group Part Number	4817603V00
Software Group Release Date	JUN2015
Software Group Description	735B

Logged Diagnostic Codes [Diagnostic Clock = 8954 hours] - Chassis 735 (T4P00266)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Display #2

Parameter	Value
ECM Part Number	336-894002
ECM Serial Number	0901G035MR

Software Group Part Number	4782933-00
Software Group Release Date	JUN2015
Software Group Description	AT CMPD

Logged Diagnostic Codes [Diagnostic Clock = 8954 hours] - Display #2

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

C15 735B (TXL00577)

Parameter	Value
Equipment ID	735B
Engine Serial Number	TXL00577
ECM Part Number	4884877-02
ECM Serial Number	11817972QM
Software Group Part Number	5766772-00
Software Group Release Date	APR19
Software Group Description	C15-735

Logged Diagnostic Codes [Diagnostic Clock = 8954 hours] - C15 735B (TXL00577)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Product Link (T4P00266)

Parameter	Value
Machine Serial Number	T4P00266
Dealer Identification Code	L030
DBS Machine Make Code	AA
ECM Serial Number	0141B654LQ
Wireless Transmission Device Serial Number	DQCAT0087029
Software Group Part Number	4761913-00
Software Group Release Date	APR2015
Software Group Description	PL300-2014B-PROD-1.0

Logged Diagnostic Codes [Diagnostic Clock = 8954 hours] - Product Link (T4P00266)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				