

Cat Electronic Technician 2019C v1.0

Product Status Report

22-1-2021 08:18

Product Status Report

Parameter	Value
Product ID	CAT00000
Equipment ID	950K
Comments	

VIMS Main Module (CAT00000)

Parameter	Value
Machine Serial Number	CAT00000
Product ID	CAT00000
Equipment ID	
ECM Part Number	3402413-03
ECM Serial Number	08329079RN
Software Group Part Number	4637660-00
Software Group Release Date	AUG14
Software Group Description	PLGSM 2014A PROD 1.0
Application Software Part Number	Unavailable
Telematic Device Software Group Part Number	5809705-00
Telematic Device Software Group Release Date	MAR2019
Telematic Device Software Group Description	PROD-4.3.11

Logged Diagnostic Codes [Diagnostic Clock = 11037 hours] - VIMS Main Module (CAT00000)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Primary Display

Parameter	Value
ECM Part Number	3293086-01
ECM Serial Number	0902J038PA
Software Group Part Number	4667403-00
Software Group Release Date	AUG2014
Software Group Description	MWL K-Series

Input/Output Module

Parameter	Value
ECM Part Number	2995744-05
ECM Serial Number	1022B110HZ
Software Group Part Number	4739695-00

Software Group Release Date	
Software Group Description	Relay Driver Module

C7.1 950 (C7R04411)

Parameter	Value
Equipment ID	950K
Engine Serial Number	C7R04411
ECM Part Number	3408157-04
ECM Serial Number	10827300QS
Software Group Part Number	5162535-00
Software Group Release Date	JUN16
Software Group Description	WHL 950
Calibration Identification Number	AD914_03

Logged Diagnostic Codes [Diagnostic Clock = 11037 hours] - C7.1 950 (C7R04411)

Code	Description	Occ.	First	Last
262- 4	5 Volt Sensor DC Power Supply : Voltage Below Normal	2	11037	11037
3405- 6	EGR Valve Control : Current Above Normal	2	11037	11037

Implement 950K (J5M00370)

Parameter	Value
Product ID	J5M00370
Equipment ID	
ECM Part Number	3045687-02
ECM Serial Number	11826192MS
Software Group Part Number	3952171-00
Software Group Release Date	JAN2012
Software Group Description	950K Implement Control (G)

Logged Diagnostic Codes [Diagnostic Clock = 11037 hours] - Implement 950K (J5M00370)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Transmission 950K (N2J00521)

Parameter	Value
Product ID	J5M00370
Equipment ID	
Transmission Serial Number	N2J00521
ECM Part Number	3045687-02
ECM Serial Number	11826252MS
Software Group Part Number	4682813-00
Software Group Release Date	OCT2014
Software Group Description	950K Transmission
Active Diagnostic Codes Present	No

Logged Diagnostic Codes [Diagnostic Clock = 11037 hours] - Transmission 950K (N2J00521)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				