

Cat Electronic Technician 2021C v1.0

Product Status Report

24-10-2022 10:32

Product Status Report

Parameter	Value
Product ID	B1M01995
Equipment ID	B1M01995
Comments	

C11 730 (RSX10745)

Parameter	Value
Product ID	B1M04002
Equipment ID	B1M04002
Engine Serial Number	RSX10745
ECM Part Number	3722905-00
ECM Serial Number	11936173JL
Software Group Part Number	4533111-00
Software Group Release Date	NOV13
Software Group Description	AT-730
Active Diagnostic Codes Present	Yes

Logged Diagnostic Codes [Diagnostic Clock = 15422 hours] - C11 730 (RSX10745)

Code	Description	Occ.	First	Last
91- 8	Throttle Position Sensor : Abnormal Frequency, Pulse Width, or Period	107	15420	15422

Monitor OHT (B1M01995)

Parameter	Value
Equipment ID	B1M01995
ECM Part Number	2395025-09
ECM Serial Number	2847B651HL
Software Group Part Number	3252574-00
Software Group Release Date	JAN08
Software Group Description	AT Messenger

Logged Diagnostic Codes [Diagnostic Clock = 15359 hours] - Monitor OHT (B1M01995)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Product Link (B1M01995)

Parameter	Value
-----------	-------

Machine Serial Number	B1M01995
Dealer Identification Code	L030
DBS Machine Make Code	AA
ECM Serial Number	2907B840LQ
Wireless Transmission Device Serial Number	DQCAT0010529
Software Group Part Number	3303409-00
Software Group Release Date	APR2008
Software Group Description	PL-300 3.1.1

Logged Diagnostic Codes [Diagnostic Clock = 15359 hours] - Product Link (B1M01995)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Transmission 730 (JRH04596)

Parameter	Value
Product ID	B1M01995
Equipment ID	B1M01995
ECM Part Number	2621408-02
ECM Serial Number	33576427JT
Software Group Part Number	4485324-00
Software Group Release Date	OCT2014
Software Group Description	730(B1M00411-up)TransType1

Logged Diagnostic Codes [Diagnostic Clock = 15359 hours] - Transmission 730 (JRH04596)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				