

# Cat Electronic Technician 2019C v1.0

## Product Status Report

1-7-2021 07:56

### Product Status Report

Parameter	Value
Product ID	KRS00465
Equipment ID	KRS00465
Comments	

### C13 980 (T4F01464)

Parameter	Value
Equipment ID	NOT PROGRAMMED
Engine Serial Number	T4F01464
ECM Part Number	4176013-00
ECM Serial Number	19646094QM
Software Group Part Number	4656909-00
Software Group Release Date	NOV14
Software Group Description	MWL 980/982 PS
Operator Inducement Regulation Configuration	Worldwide

### Logged Diagnostic Codes [Diagnostic Clock = 11740 hours] - C13 980 (T4F01464)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

### Implement 980M (KRS00465)

Parameter	Value
Product ID	KRS00465
Equipment ID	
ECM Part Number	3656773-04
ECM Serial Number	19046137VD
Software Group Part Number	4910945-00
Software Group Release Date	NOV2015
Software Group Description	980 Implement

### Logged Diagnostic Codes [Diagnostic Clock = 11740 hours] - Implement 980M (KRS00465)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

### Diesel Exhaust Fluid Controller #1

Parameter	Value
Aftertreatment #1 DEF Dosing System Serial Number	PET008577T
Application Software Part Number	4410634-00

### Engine #1 Aftertreatment Controller

Parameter	Value
Equipment ID	NOT PROGRAMMED
Engine Serial Number	T4F01464
ECM Serial Number	13547242QU
Software Group Part Number	4654045-00
Software Group Release Date	SEP14
Software Group Description	AFT_T4F_C13_HWA_A5E2V1

### Logged Diagnostic Codes [Diagnostic Clock = 11740 hours] - Engine #1 Aftertreatment Controller

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

### Transmission 980M (HDS00475)

Parameter	Value
Product ID	KRS00465
Equipment ID	
Transmission Serial Number	HDS00475
ECM Part Number	3656790-04
ECM Serial Number	19046051QQ
Software Group Part Number	4912415-00
Software Group Release Date	NOV2015
Software Group Description	980 Transmission
Active Diagnostic Codes Present	No

### Logged Diagnostic Codes [Diagnostic Clock = 11740 hours] - Transmission 980M (HDS00475)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

### Indication Display

Parameter	Value
ECM Part Number	3743614-02
ECM Serial Number	17048013DT
Software Group Part Number	4488243-00
Software Group Release Date	AUG2013
Software Group Description	Indication Display

### Input/Output Module

Parameter	Value
ECM Part Number	2995744-05

ECM Serial Number	1824B103HZ
Software Group Part Number	4805894-00
Software Group Release Date	SEP2015
Software Group Description	Relay Driver Module

### VIMS Main Module (KRS00465)

Parameter	Value
Machine Serial Number	KRS00465
Product ID	KRS00465
Equipment ID	KRS00465
ECM Part Number	3402413-05
ECM Serial Number	14049074RN
Software Group Part Number	4637660-00
Software Group Release Date	AUG14
Software Group Description	PLGSM 2014A PROD 1.0
Application Software Part Number	Unavailable
Telematic Device Software Group Part Number	5809705-00
Telematic Device Software Group Release Date	MAR2019
Telematic Device Software Group Description	PROD-4.3.11

### Logged Diagnostic Codes [Diagnostic Clock = 11740 hours] - VIMS Main Module (KRS00465)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

### Graphical Display (KRS00465)

Parameter	Value
ECM Part Number	4415131-00
ECM Serial Number	1954G009UU
Software Group Part Number	4780957-00
Software Group Release Date	JUL2015
Software Group Description	MWL_20.454_Jul.02.2015

### Logged Diagnostic Codes - Graphical Display (KRS00465)

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				