

Cat Electronic Technician 2021C v1.0

Product Status Report

22-12-2021 07:54

Product Status Report

Parameter	Value
Product ID	B1P02175
Equipment ID	740
Comments	

Transmission 740 (B1P02175)

Parameter	Value
Product ID	B1P02175
Equipment ID	740
ECM Part Number	3045687-01
ECM Serial Number	24286014MS
Software Group Part Number	4485324-00
Software Group Release Date	OCT2014
Software Group Description	740 (B1P00622 up)

Logged Diagnostic Codes [Diagnostic Clock = 17281 hours] - Transmission 740 (B1P02175)

Code	Description	Occ.	First	Last
971- 5	Interaxle Differential Lock Solenoid : Current Below Normal	127	15755	17281

C15 740 (LHX12050)

Parameter	Value
Product ID	B1P02418
Equipment ID	B1P02418
Engine Serial Number	LHX12050
ECM Part Number	2622878-01
ECM Serial Number	03076245JL
Software Group Part Number	3209657-00
Software Group Release Date	MAR08
Software Group Description	AT-740
Active Diagnostic Codes Present	Yes

Logged Diagnostic Codes [Diagnostic Clock = 17775 hours] - C15 740 (LHX12050)

Code	Description	Occ.	First	Last
91- 8	Throttle Position Sensor : Abnormal Frequency, Pulse Width, or Period	53	17771	17774