

CATERPILLAR 950K

Description

Caterpillar 950K, Engine Caterpillar C7.1, 163kW, CE, Air conditioning, Erops cabin, 23.5 R25 tyres, GP bucket with bolt on edge, Width of the bucket 2.90m, 3th valve, Complete steering wheel, Ride control, Autoshift, Backup camera, Central lubrication, Beacon, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



Year	2012
Hours	11036
Weight	19300 kg
Serial number	CAT0950KEJ5M00370
Reference	182002

[Download photos](#)



CONTACT US:
 SALES@SMITMA.COM
 +31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine	Caterpillar C7.1,
Engine power	163kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	C7R04411
Arrangement number	328-1575
Air cleaner	Clean
Anti-freeze level °C	- 35
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No

Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★
Teeth	★★★★★

FRAME

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★

Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Drivetrain leaks	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes

SAFETY ITEMS

Seat belt	Available
Horn	Working
Beacon	Working

TYRES

FRONT LEFT

Percentage life remaining	90%
Retreaded	Yes

REAR LEFT

Percentage life remaining	90%
---------------------------	-----

Retreaded Yes

REAR RIGHT

Percentage life remaining 90%

Retreaded Yes

FRONT RIGHT

Percentage life remaining 90%

Retreaded Yes

New/Excellent



Very good



Good



Fair



Poor

