

HAMM 3516

Description

Hamm 3516, Deutz TCD 2012 L04 2V, 155kW, EPA, CE, Erops cabin, 23.1 - 26 tyres, Compaction meter, Frequency meter, Speed meter, In very good and clean condition.



Year	2011
Hours	2269
Weight	15755
Serial number	H1761524
Reference	181672

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Deutz TCD 2012 L04 2V,
Engine power in kW	155kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Bonnet	★★★★☆☆
Chassis	★★★★☆☆
Steps/ladders	★★★★☆☆
Cabin	★★★★☆☆

ENGINE DETAILS AND CONDITION

Engine number	11003466
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	- 46
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No

Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warnings	Warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Leakages	No
Drum oil level ok	Yes

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
------------------------	-----

Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

DRIVE CHAIN

Oil level rear axle ok	Yes
Rear axle leakages	No
Wheel bolts and rims	★★★★★
Travel motors	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes

TYRES

REAR LEFT TYRES

Percentage life remaining 40%

REAR RIGHT TYRES

Percentage life remaining 40%

New/Excellent ★★★★★	Very good ★★★★★	Good ★★★★★	Fair ★★★★★	Poor ★★★★★
------------------------	--------------------	---------------	---------------	---------------

