

HAMM 3520

Description

Hamm 3520, Deutz TCD 2012 L06 2V, 155kW, EPA, CE, Erops cabin, 23.1 - 26 tyres, Frequency meter, Speed meter, Air conditioning, Backup alarm, In good and clean condition.



Year	2009
Hours	4371
Weight	19800 kg
Serial number	H1761188
Reference	181710

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Deutz
Engine model	TCD 2012 L06 2V,
Engine power in kW	155kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	10714543
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-26
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Water in the oil	No
Oil in the water	No
Smoke	Normal

Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warnings	Warnings available
Mirrors	Small crack, no need to repair
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★
Leakages	No
Drum oil level ok	Yes

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★

Play articulating point



HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆

DRIVE CHAIN

Oil level rear axle ok	Yes
Rear axle leakages	No
Wheel bolts and rims	★★★★☆
Travel motors	★★★★☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	Yes

TYRES

REAR LEFT TYRES

Percentage life remaining 60%

REAR RIGHT TYRES

Percentage life remaining 60%

New/Excellent



Very good



Good



Fair



Poor

