

CATERPILLAR M318D

Description

Caterpillar M318D, Engine brand Caterpillar C6.6, 130kW, EPA, CE, Air conditioning, Central lubrication, Beacon, Tyre size 11.00 - 20 tyres, Mono boom, New digging bucket with teeth, Width of the bucket 1.20m, Piped for hammer, shear and clamp, Burst valve on lift and stick cylinder, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



Year 2008

Hours 15864

Weight

Serial number CATM318DTW8P00923

Reference 181993



[Download photos](#)

CONTACT US:
 SALES@SMITMA.COM
 +31(0)773999840

New/Excellent
 ★★★★★

Very good
 ★★★★★

Good
 ★★★★★

Fair
 ★★★★★

Poor
 ★★★★★



INSPECTION REPORT

FEATURES

Engine brand	Caterpillar C6.6,
Engine power in kW	130kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Counter weight	★★★★★
Toolbox	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	C6E12770
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	- 35
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes

Engine power	★★★★★
Blow by	★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★
Fan	★★★★
Radiator	★★★★

BUCKET

Overall condition of the bucket	★★★★★★
Bottom	★★★★★★
Sides	★★★★★★
Cutting edge	★★★★★★
Teeth	★★★★★★

SAFETY ITEMS

Seat belt	Available
Horn	Working
Beacon	Working

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BOOM AND STICK

Play lift cylinder	★★★★★
Lift cylinders leaking	No
Play boom pen	★★★★★
Play stick cylinder	★★★★★
Stick cylinder leaking	No
Play stick pen	★★★★★
Play bucket cylinder	★★★★★
Bucket cylinder leaking	No
Play bucket link	★★★★★
Play bucket pen	★★★★★
Condition monoboam	★★★★★
Condition stick	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
------------------------	-----

Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Additional lights working	Yes

TYRES

FRONT LEFT

Percentage life remaining 30%

REAR LEFT

Percentage life remaining 60%

REAR RIGHT

Percentage life remaining 60%

FRONT RIGHT

Percentage life remaining 30%

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV

