

CATERPILLAR M318D MH

Description

Caterpillar M318D MH, Engine brand Caterpillar C6.6, 129kW, CE, Air conditioning, Central lubrication, Tyre size 10.00 - 20 tyres, Straight boom, Stick Hydraulic elevated cabin, Burst valve on lift and stick cylinder, Hours certified by Caterpillar, In good and clean condition.



Year	2008
Hours	14284
Weight	
Serial number	CATM318DEW8R00262
Reference	181991

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine brand	Caterpillar C6.6,
Engine power in kW	129kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Body work	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Counter weight	★★★☆☆
Toolbox	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★☆☆
Cracks or welds	No

ENGINE DETAILS AND CONDITION

EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	- 31
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★☆
Engine supports	★★★★☆
Hoses	★★★★☆

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆

BOOM AND STICK

Play lift cylinder	★★★★☆
Lift cylinders leaking	No
Play boom pen	★★★★☆
Play stick cylinder	★★★★☆
Stick cylinder leaking	No
Play stick pen	★★★★☆
Play bucket pen	★★★★☆
Condition monoboam	★★★★☆
Condition stick	★★★★☆

SWING CIRKLE

Play on the swing bearing	★★★★☆
Swing gear	★★★★☆
Swing brake operating	Yes
Swing noice normal	Yes
Operating condition	★★★★☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆

TYRES

FRONT LEFT

Percentage life remaining	20%
---------------------------	-----

REAR LEFT

Percentage life remaining 40%

REAR RIGHT

Percentage life remaining 40%

FRONT RIGHT

Percentage life remaining 20%

New/Excellent ★ ★ ★ ★ ★	Very good ★ ★ ★ ★ ☆	Good ★ ★ ★ ☆ ☆	Fair ★ ★ ☆ ☆ ☆	Poor ★ ☆ ☆ ☆ ☆
----------------------------	------------------------	-------------------	-------------------	-------------------

Copyright Smitma BV

