

CATERPILLAR 336D LN

Description

Caterpillar 336D LN, Engine brand Caterpillar C9, 200kW, CE, Emission level Stage IIIA, Air conditioning, Central lubrication, Cabin protection, Cat walk, Width of the pads 600mm, Straight boom, Length of the stick 3.50m, New digging bucket with teeth, Piped for hammer, shear and clamp, Burst valve on lift and stick cylinder, AM/FM Radio, Hours certified by Caterpillar, In very good and clean condition.



Year	2010
Hours	12800
Weight	39400 kg
Serial number	CAT0336DEMYG00198
Reference	181617

[Download photos](#)


CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV



INSPECTION REPORT

FEATURES

Engine brand	Caterpillar C9,
Engine power in kW	200kW,
Emission level	Stage IIIA,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Bottom plates	★★★★★
Counter weight	★★★★★
Toolbox	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Pre-cleaner bowl	★★★★★
Central greasing working	Yes

ENGINE DETAILS AND CONDITION

Engine number	THX27021
Arrangement number	224-9843
Air cleaner	Clean
Anti-freeze level °C	- 46
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★

Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

BUCKET

Overall condition of the bucket	★★★★★★
Bottom	★★★★★★
Sides	★★★★★★
Cutting edge	★★★★★★
Teeth	★★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	70/80% good
Chains	70%
Bushings	70%
Sprockets	70%
Idlers	80%
Bottom rollers	70%
Top rollers	80%
Track pads	80%

SAFETY ITEMS

Backup camera	Not Working
Note: Hij heeft het wel maar werkt niet	
Seat belt	Not Available
Horn	Working

OPERATOR STATION

Hourmeter

Working, hours certified by Caterpillar

Note: Only working in display

Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

SWING CIRCLE

Play on the swing bearing	★★★★★
Swing gear	★★★★★
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★★

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆☆
Batteries	★★★★☆☆
Starter	★★★★☆☆
Cabin lights working	Yes

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★☆☆

Fair
★★★☆☆

Poor
★★★★☆

Copyright Smitma BV

TRUSTED

SINCE 1960

PARTNER