

CATERPILLAR 950K HIGH LIFT

Description

Caterpillar 950K, Engine Caterpillar C7.1, 163kW, EPA, CE, Air conditioning, Erops cabin, 23.5 R25 NEW front tyres, rear tyres 30% good, GP bucket with bolt on edge, Width of the bucket 2.80m, Complete steering wheel, Ride control, Autoshift, Backup camera, Weight load indicator, Central lubrication, Beacon, AM/FM radio, Hours certified by Caterpillar, In very good and clean condition.



Year 2013

Hours 7107

Weight

Serial number CAT0950KEJ5M01034

Reference 180841



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
 ★★★★★

Very good
 ★★★★★★

Good
 ★★★★★★

Fair
 ★★★★★★

Poor
 ★★★★★★



INSPECTION REPORT

FEATURES

| | |
|--------------|-------------------|
| Engine | Caterpillar C7.1, |
| Engine power | 163kW, |

GENERAL APPEARANCE

| | |
|-------------------------------|-------|
| Stamped serial number checked | Yes |
| Serial number plate checked | Yes |
| Paint | ★★★★☆ |
| Decals | ★★★★★ |
| Bonnet | ★★★★☆ |
| Chassis | ★★★★☆ |
| Steps/ladders | ★★★★☆ |
| Grab irons | ★★★★☆ |
| Cabin | ★★★★☆ |
| Central greasing working | Yes |

ENGINE DETAILS AND CONDITION

| | |
|-----------------------------|----------|
| Engine number | C7R08023 |
| Arrangement number | 328-1575 |
| Air cleaner | Clean |
| Anti-freeze level °C | - 50 |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★☆ |
| Muffler | ★★★★☆ |
| Exhaust stack | ★★★★☆ |
| Engine supports | ★★★★☆ |
| Hoses | ★★★★☆ |
| Good cold start | Yes |
| Engine power | ★★★★☆ |
| Blow by | ★★★★☆ |
| Knocking | No |
| Compression in the radiator | No |

| | |
|-------------------|--------|
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |
| Belts and pulleys | ★★★★☆ |
| Fan | ★★★★☆ |
| Radiator | ★★★★☆ |

OPERATOR STATION

| | |
|-------------------|---|
| Hourmeter | Working, hours certified by Caterpillar |
| Air conditioning | Working |
| Heater | Working |
| Gauges | Working |
| Switches | ★★★★☆ |
| Display | ★★★★☆ |
| Warning | No warnings available |
| Mirrors | Not broken |
| Cabin glass | Not broken |
| Windshield wipers | Working |
| Interior lights | Not working |
| Cabin floor | ★★★★☆ |
| Interior roof | ★★★★☆ |
| Seat | ★★★☆☆ |

BUCKET

| | |
|---------------------------------|-------|
| Overall condition of the bucket | ★★★★☆ |
| Bottom | ★★★★☆ |
| Sides | ★★★★☆ |
| Cutting edge | ★★★★☆ |

FRAME

| | |
|-------------------------|-------|
| Play articulation point | ★★★★☆ |
| Play loading frame | ★★★★☆ |
| Play bucket pins | ★★★★☆ |
| Crack or welds | No |

HYDRAULICS

| | |
|------------------------------|-------|
| Hydraulic oil level ok | Yes |
| Hydraulic lines and fittings | ★★★★☆ |

| | |
|------------------------------------|-------|
| Hydraulic tank/sight glass and cap | ★★★★★ |
| Hydraulic valves leaking | No |
| Noise hydraulic pump normal | Yes |
| Operating condition hydraulics | ★★★★★ |

BRAKE

| | |
|-------------------------|-------|
| Brakelines | ★★★★★ |
| Service brake operation | ★★★★★ |
| Parking brake operation | ★★★★★ |
| Compressor | ★★★★★ |

DRIVE TRAIN/TRANSMISSION

| | |
|---|-----|
| Transmission fully operational in all gears forward and reverse | Yes |
| Transmission oil level ok | Yes |
| Transmission noisy | No |
| Oil level front axle ok | Yes |
| Oil level rear axle ok | Yes |
| Drivetrain leaks | No |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|------------------------|-------|
| Alternator functioning | Yes |
| Wiring | ★★★★★ |
| Batteries | ★★★★★ |
| Starter | ★★★★★ |
| Cabin lights working | Yes |

SAFETY ITEMS

| | |
|-----------|-----------|
| Seat belt | Available |
| Horn | Working |

| | | | | |
|------------------------|--------------------|---------------|---------------|---------------|
| New/Excellent ★★★★★ | Very good ★★★★★ | Good ★★★★★ | Fair ★★★★★ | Poor ★★★★★ |
|------------------------|--------------------|---------------|---------------|---------------|

