

## CATERPILLAR 336DL

### Description

Caterpillar 336D L, Engine brand Caterpillar C9, 200kW, CE, Emission level Stage IIIA, Backup camera, Width of the pads 600mm, Mono boom, New digging bucket with teeth, Width of the bucket 1.50m, Piped for hammer, Hours certified by Caterpillar: 11177H, In very good and very clean condition.



Year	2010
Hours	9675
Weight	39400 kg
Serial number	CAT0336DCPPN00398
Reference	181217

[Download photos](#)



CONTACT US:  
 SALES@SMITMA.COM  
 +31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



# INSPECTION REPORT

---

## FEATURES

Engine brand	Caterpillar C9,
Engine power in kW	200kW,
Emission level	Stage IIIA,

## GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Body work	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Bottom plates	★★★★★
Counter weight	★★★★★
Toolbox	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★
Cracks or welds	No

## ENGINE DETAILS AND CONDITION

Engine number	THX27505
Arrangement number	224-9843
Air cleaner	Clean
Anti-freeze level °C	-25
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★

Hoses	★★★★☆
Good cold start	Yes
Engine power	★★★★☆
Blow by	★★★★☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

## BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★
Teeth	★★★★★

## UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	80% good
Chains	80%
Bushings	80%
Sprockets	80%
Idlers	80%
Bottom rollers	70%
Top rollers	80%
Track pads	70%

## SAFETY ITEMS

Backup camera	Working
Seat belt	Available
Horn	Working

## OPERATOR STATION

Hourmeter	Working
Note: Only in display	

Air conditioning	Not Working
Heater	Not Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warning	No warnings available
Cabin glass	Not broken
Windshield wipers	Not Working
Interior lights	Working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★★

## HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Travel motors	★★★★☆
High and low travel speed working	Working
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆

## BOOM AND STICK

Play lift cylinder	★★★★☆
Lift cylinders leaking	No
Play boom pen	★★★★☆
Play stick cylinder	★★★★☆
Stick cylinder leaking	No
Play stick pen	★★★★☆
Play bucket cylinder	★★★★☆
Bucket cylinder leaking	No
Play bucket link	★★★★☆
Play bucket pen	★★★★☆
Condition monoboam	★★★★☆

Condition stick



## SWING CIRCLE

Play on the swing bearing	★★★★☆
Swing gear	★★★★☆
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★☆

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★★
Starter	★★★★☆

New/Excellent  
★★★★★

Very good  
★★★★☆

Good  
★★★★☆

Fair  
★★★☆☆

Poor  
★★☆☆☆

