

HAMM HD90

Description

Hamm HD+90 VO, Deutz TCD 2012 L04 2V, 100kW, Width of the drum 1.67m, EPA, CE, Erops cabin, Both drum vibrating, Oscillation compaction, Moveable seat, Frequency meter, Air conditioning, In very good and very clean condition.



Year	2013
Hours	3192
Weight	9380 kg
Serial number	H1850680
Reference	181673



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Deutz TCD 2012 L04 2V,
Engine power in kW	100kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Engine cover doors	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	11143445
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	- 35
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal

Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warning	No Warnings Available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★☆☆
Interior roof	★★★★☆
Seat	★★★★☆

FRONT DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆
Drum scrapers	★★★★☆
Travel motors	★★★★☆

REAR DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆
Drum scrapers	★★★★☆
Travel motors	★★★★☆

STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★☆
Play articulating point	★★★★☆

Steering cylinders leaking	No
Play steering cylinders	★★★★☆

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★☆
Hydraulic tank/sight glass and cap	★★★★☆
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	Yes

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★★☆

Fair
★★★☆☆

Poor
★★☆☆☆

