

HAMM 3516P


Description

Hamm 3516P, Deutz TCD 2012 L06 2V, 155kW, EPA, CE, Erops cabin, 23.1 - 26 tyres, Frequency meter, Speed meter, Air conditioning, In very good and clean condition.



| | |
|---------------|----------|
| Year | 2010 |
| Hours | 3110 |
| Weight | 15855 |
| Serial number | H1761468 |
| Reference | 181361 |

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

| | | | | |
|------------------------|--------------------|---------------|---------------|---------------|
| New/Excellent ★★★★★ | Very good ★★★★☆ | Good ★★★☆☆ | Fair ★★★☆☆ | Poor ★★☆☆☆ |
|------------------------|--------------------|---------------|---------------|---------------|



INSPECTION REPORT

FEATURES

| | |
|--------------------|------------------------|
| Engine brand | Deutz TCD 2012 L06 2V, |
| Engine power in kW | 155kW, |

GENERAL APPEARANCE

| | |
|-------------------------------|--------|
| Stamped serial number checked | Yes |
| Serial number plate checked | Yes |
| Paint | ★★★★☆☆ |
| Decals | ★★★★☆☆ |
| Bonnet | ★★★★☆☆ |
| Chassis | ★★★★☆☆ |
| Steps/ladders | ★★★★☆☆ |
| Cabin | ★★★★☆☆ |

ENGINE DETAILS AND CONDITION

| | |
|-----------------------------|----------|
| Engine number | 10977134 |
| Air cleaner | New |
| Anti-freeze level °C | - 35 |
| Diesel anti-freeze added | Yes |
| Diesel level ok | Yes |
| Cooling liquid level ok | Yes |
| Engine oil level ok | Yes |
| Exhaust manifold | ★★★★☆☆ |
| Muffler | ★★★★☆☆ |
| Exhaust stack | ★★★★☆☆ |
| Hoses | ★★★★☆☆ |
| Good cold start | Yes |
| Engine power | ★★★★☆☆ |
| Blow by | ★★★★☆☆ |
| Knocking | No |
| Compression in the radiator | No |
| Water in the oil | No |
| Oil in the water | No |
| Smoke | Normal |
| Engine leaks | No |

| | |
|-------------------|-------|
| Belts and pulleys | ★★★★★ |
| Fan | ★★★★★ |
| Radiator | ★★★★★ |

OPERATOR STATION

| | |
|-------------------|-----------------------|
| Hourmeter | Working |
| Air conditioning | Not Working |
| Heater | Working |
| Gauges | Working |
| Switches | ★★★★★ |
| Display | ★★★★★ |
| Warnings | No warnings available |
| Mirrors | Not broken |
| Cabin glass | Not broken |
| Windshield wipers | Working |
| Interior lights | Working |
| Cabin floor | ★★★★★ |
| Interior roof | ★★★★★ |
| Seat | ★★★★★ |

DRUM

| | |
|-------------------|-------|
| Vibratory system | ★★★★★ |
| Drum surface | ★★★★★ |
| Rubber mounts | ★★★★★ |
| Drum scrapers | ★★★★★ |
| Leakages | No |
| Drum oil level ok | Yes |

HYDRAULICS

| | |
|------------------------------------|-------|
| Hydraulic oil level ok | Yes |
| Hydraulic lines and fittings | ★★★★★ |
| Hydraulic tank/sight glass and cap | ★★★★★ |
| Noise hydraulic pump normal | Yes |
| Operating condition hydraulics | ★★★★★ |

DRIVE CHAIN

| | |
|------------------------|-------|
| Oil level rear axle ok | Yes |
| Rear axle leakages | No |
| Wheel bolts and rims | ★★★★★ |

| | |
|--------------------------------|--------|
| Travel motors | ★★★★★★ |
| Oil level left final drive ok | Yes |
| Left final drive leaking | No |
| Oil level right final drive ok | Yes |
| Right final drive leaking | No |

ELECTRICAL, STARTING AND CHARGING SYSTEM

| | |
|------------------------|--------|
| Alternator functioning | Yes |
| Wiring | ★★★★★★ |
| Batteries | ★★★★★★ |
| Starter | ★★★★★★ |
| Cabin lights working | Yes |

TYRES

REAR LEFT TYRES

Percentage life remaining 70%

REAR RIGHT TYRES

Percentage life remaining 70%

| | | | | |
|-------------------------|---------------------|----------------|----------------|----------------|
| New/Excellent ★★★★★★ | Very good ★★★★★★ | Good ★★★★★★ | Fair ★★★★★★ | Poor ★★★★★★ |
|-------------------------|---------------------|----------------|----------------|----------------|

