

CATERPILLAR 962M HL

Description

Caterpillar 962M high lift, Engine Caterpillar C7.1, 201kW, EPA, Emission level Stage IV, CE, Air conditioning, Erops cabin, 23.5 R25 Goodyear tyres, GP bucket with bolt on edge, Width of the bucket 2.90m, Complete steering wheel, Ride control, Autoshift, Backup camera, Backup alarm, Weight load indicator, Central lubrication, AM/FM radio, Hours certified by Caterpillar, In very good and very clean condition.



Year 2015

Hours 9689

Weight

Serial number CAT0962MTF2T00365

Reference 182771

[Download photos](#)



CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent
 ★★★★★

Very good
 ★★★★★★

Good
 ★★★★★★

Fair
 ★★★★★★

Poor
 ★★★★★★



INSPECTION REPORT

FEATURES

Engine	Caterpillar C7.1,
Engine power	201kW,
Emission level	Stage IV,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Bonnet	★★★★★
Chassis	★★★★★
Steps/ladders	★★★★★
Grab irons	★★★★★
Cabin	★★★★★

ENGINE DETAILS AND CONDITION

Engine number	D8T11262
Arrangement number	476-3227
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	- 35
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No

Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

FRAME

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
------------------------	-----

Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Brakelines	★★★★★
Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes
Drivetrain leaks	No

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working

TYRES

FRONT LEFT	
Tread dept in mm	44mm
Percentage life remaining	80%
Retreaded	No

REAR LEFT

Tread dept in mm	15mm
Percentage life remaining	28%
Retreaded	No

REAR RIGHT

Tread dept in mm	21mm
Percentage life remaining	38%
Retreaded	No

FRONT RIGHT

Tread dept in mm	46mm
Percentage life remaining	84%
Retreaded	No

New/Excellent



Very good



Good



Fair



Poor

