

LIEBHERR R914C HD-SL

Description

Liebherr R914C HD-SL, Engine brand Liebherr D934, 115kW, EPA, CE, Air conditioning, Central lubrication, Width of the pads 600mm, Mono boom, Piped for hammer & shear, Burst valve on lift cylinder, In good and clean condition.



Year	2008
Hours	11857
Weight	24000
Serial number	WLHZ1063TZC024232
Reference	182263



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Liebherr D934,
Engine power in kW	115kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Body work	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Bottom plates	★★★★☆
Counter weight	★★★★☆
Toolbox	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★★☆
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	2008 03 2746
Air cleaner	Clean
Anti-freeze level °C	- 41
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★☆
Engine supports	★★★★☆
Hoses	★★★★☆
Good cold start	Yes

Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

UNDERCARRIAGE LEFT IN LIFE IN %

Overall condition	50% good
Chains	70%
Bushings	70%
Sprockets	60%
Idlers	60%
Bottom rollers	10%
Top rollers	40%
Track pads	60%

OPERATOR STATION

Hourmeter	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Cabin glass	Small crack, no need to repair
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
High and low travel speed working	Working

Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes
Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆☆

BOOM AND STICK

Play lift cylinder	★★★★☆☆
Lift cylinders leaking	No
Play boom pen	★★★★☆☆
Play stick cylinder	★★★★☆☆
Stick cylinder leaking	No
Play stick pen	★★★★☆☆
Play bucket cylinder	★★★★☆☆
Bucket cylinder leaking	No
Play bucket link	★★★★☆☆
Play bucket pen	★★★★☆☆
Condition monoboom	★★★★☆☆
Condition stick	★★★★☆☆

SWING CIRCLE

Play on the swing bearing	★★★★☆☆
Swing gear	★★★★☆☆
Swing drive oil level ok	Yes
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★☆☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆☆
Batteries	★★★★☆☆
Starter	★★★★☆☆
Cabin lights working	Yes

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV

