

## CATERPILLAR M318C MH

### Description

Caterpillar M318C MH, Engine brand Caterpillar 3056, 129,5kW, EPA, CE, Air conditioning, Tyre size 10.00-20 tyres, Straight boom, Stick Hydraulic elevated cabin, Piped for clamp, Burst valve on lift and stick cylinder, AM/ FM radio, Hours certified by Caterpillar, Generator, In good and clean condition.



Year	2005
Hours	10772
Weight	
Serial number	CATM318CEH2F00136
Reference	182743

[Download photos](#)



**CONTACT US:**  
**SALES@SMITMA.COM**  
**+31(0)773999840**

New/Excellent



Very good



Good



Fair



Poor



# INSPECTION REPORT

---

## FEATURES

Engine brand	Caterpillar 3056,
Engine power in kW	129,5kW,

## GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Body work	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Engine cover doors	★ ★ ★ ★ ★
Chassis	★ ★ ★ ★ ★
Counter weight	★ ★ ★ ★ ★
Steps/ladders	★ ★ ★ ★ ★
Grab irons	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★
Pre-cleaner bowl	★ ★ ★ ★ ★
Cracks or welds	No

## ENGINE DETAILS AND CONDITION

Engine number	188-5096
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-16
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★ ★ ★ ★ ★
Muffler	★ ★ ★ ★ ★
Exhaust stack	★ ★ ★ ★ ★
Engine supports	★ ★ ★ ★ ★
Hoses	★ ★ ★ ★ ★
Good cold start	Yes

Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

## SAFETY ITEMS

Seat belt	Available
Horn	Working

## OPERATOR STATION

Hourmeter	Working, hours certified by Caterpillar
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Interior lights	Working
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

## HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes

Right final drive leaking	No
Noise hydraulic pump normal	No
Operating condition hydraulics	★★★★☆

### BOOM AND STICK

Play lift cylinder	★★★★☆
Lift cylinders leaking	No
Play boom pen	★★★★☆
Play stick cylinder	★★★★☆
Stick cylinder leaking	No
Play stick pen	★★★★☆
Condition monoboom	★★★★☆
Condition stick	★★★★☆

### SWING CIRKLE

Play on the swing bearing	★★★☆☆
Swing gear	★★★★☆
Swing drive leaking	No
Swing brake operating	Yes
Swing noice normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★☆

### ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	Yes
Tail lights working	No
Additional lights working	Yes

New/Excellent  
★★★★★

Very good  
★★★★☆

Good  
★★★★☆

Fair  
★★★☆☆

Poor  
★★☆☆☆

