

CATERPILLAR M318C

Description

Caterpillar M318C, Engine brand Caterpillar 3056, 118.5kW, CE, Tyre size 10.00 - 20 NEW tyres, V/A boom, Hydraulic quick release, Digging bucket with edge, Width of the bucket 800mm, Piped for hammer & shear, Burst valve on lift cylinder, AM/FM radio, Hours checked by Caterpillar: 19297H, In very good and clean condition.



Year	2004
Hours	15848
Weight	19000 kg
Serial number	CATM318CEBCZ00308
Reference	182334



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine brand	Caterpillar 3056,
Engine power in kW	118.5kW,

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Body work	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Counter weight	★★★★☆
Toolbox	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★★☆
Cracks or welds	No

ENGINE DETAILS AND CONDITION

Engine number	CPT00485
Air cleaner	Clean
Anti-freeze level °C	- 34
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★☆
Engine supports	★★★★☆
Hoses	★★★★☆
Good cold start	Yes
Engine power	★★★★☆

Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

OPERATOR STATION

Hourmeter	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Not Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Travel motors	★★★★★
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes

Right final drive leaking	No
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★☆

BOOM AND STICK

Play lift cylinder	★★★★☆
Lift cylinders leaking	No
Play boom pen	★★★★☆
Play V/A boom pins	★★★★☆
Play V/A cylinder	★★★★☆
V/A cylinder leaking	No
Play stick cylinder	★★★★☆
Stick cylinder leaking	No
Play stick pen	★★★★☆
Play bucket cylinder	★★★★☆
Bucket cylinder leaking	No
Play bucket link	★★★☆☆
Play bucket pen	★★★★☆
Condition monoboom	★★★★☆
Condition V/A boom	★★★★☆
Condition stick	★★★★☆

SWING CIRCLE

Play on the swing bearing	★★★★☆
Swing gear	★★★★☆
Swing drive leaking	No
Swing brake operating	Yes
Swing noise normal	Yes
Hydraulic swivel leaking	No
Operating condition	★★★★☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	No

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV