

Cat Electronic Technician 2019C v1.0

Product Status Report

25-9-2020 07:52

Product Status Report

Parameter	Value
Product ID	W8P01047
Equipment ID	W8P01047
Comments	

Monitor System

Parameter	Value
ECM Part Number	2785276-05
Software Group Part Number	3594783-00
Software Group Release Date	JAN2004
Software Group Description	WEX Monitor

Soft-Switch Panel

Parameter	Value
ECM Part Number	2526696-01
Software Group Part Number	2785286-00
Software Group Release Date	JUL2005
Software Group Description	WEX Soft Switch Panel

Product Link

Parameter	Value
Machine Serial Number	
Dealer Identification Code	
DBS Machine Make Code	AA
ECM Serial Number	1748B336LQ
Wireless Transmission Device Serial Number	DQCAT0013140
Software Group Part Number	3303409-00
Software Group Release Date	APR2008
Software Group Description	PL-300 3.1.1

Logged Diagnostic Codes [Diagnostic Clock = 9182 hours] - Product Link

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

Machine Control M318D (W8P01047)

Parameter	Value
Equipment ID	W8P01047

ECM Serial Number	17287328MS
Software Group Part Number	3968973-00
Software Group Release Date	APR2012
Software Group Description	WEX M318D

Logged Diagnostic Codes [Diagnostic Clock = 9182 hours] - Machine Control M318D (W8P01047)

Code	Description	Occ.	First	Last
726- 5	Right Steering Solenoid : Current Below Normal	63	9166	9182
727- 5	Left Steering Solenoid : Current Below Normal	61	9167	9182
2543- 3	Joystick Steering Enable Switch : Voltage Above Normal	72	9175	9182
2684- 5	Ride Control Solenoid #3 : Current Below Normal	58	9175	9182

Implement Control #2

Parameter	Value
ECM Serial Number	17786482MT
Software Group Part Number	3216283-00
Software Group Release Date	JAN2008
Software Group Description	IMPLEMENT CONTROL

Logged Diagnostic Codes [Diagnostic Clock = 9182 hours] - Implement Control #2

Code	Description	Occ.	First	Last
No Logged Diagnostic Codes				

C6.6 M318D (C6E15069)

Parameter	Value
Equipment ID	W8P01047
Engine Serial Number	C6E15069
ECM Part Number	3317539-00
ECM Serial Number	18386466MB
Software Group Part Number	5012025-00
Software Group Release Date	2015
Software Group Description	WEX D Series

Logged Diagnostic Codes [Diagnostic Clock = 9182 hours] - C6.6 M318D (C6E15069)

Code	Description	Occ.	First	Last
100- 3	Engine Oil Pressure Sensor : Voltage Above Normal	2	9182	9182