

# HAMM 3412

## Description

Hamm 3412, Deutz TCD 2012 L04 2V, 100kW, EPA, CE, Erops cabin, 23.1 - 26 tyres, Compaction meter, Frequency meter, Speed meter, Backup alarm, Hours checked with diagnostic computer, In very good and clean condition.



<b>Year</b>	2011
<b>Hours</b>	2543
<b>Weight</b>	12200
<b>Serial number</b>	H1801748
<b>Reference</b>	181674

[Download photos](#)



**CONTACT US:**  
**SALES@SMITMA.COM**  
**+31(0)773999840**

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★☆☆☆
------------------------	--------------------	---------------	---------------	---------------



# INSPECTION REPORT

---

## FEATURES

Engine brand	Deutz TCD 2012 L04 2V,
Engine power in kW	100kW,

## GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆☆
Bonnet	★★★★☆☆
Chassis	★★★★☆☆
Steps/ladders	★★★★☆☆
Cabin	★★★★☆☆

## ENGINE DETAILS AND CONDITION

Engine number	11019938
Air cleaner	New
Anti-freeze level °C	- 25
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆☆
Muffler	★★★★☆☆
Exhaust stack	★★★★☆☆
Hoses	★★★★☆☆
Good cold start	Yes
Engine power	★★★★☆☆
Blow by	★★★★☆☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆☆

Fan	★★★★★
Radiator	★★★★★

## SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Parking brake	Working

## OPERATOR STATION

Hourmeter	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warnings	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Not Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★

## DRUM

Vibratory system	★★★★★
Drum surface	★★★★★
Rubber mounts	★★★★★
Drum scrapers	★★★★★

## STEERING

Articulate cylinder leaking	No
Play articulate cylinder	★★★★★
Play articulating point	★★★★★

## HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

## ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★☆
Batteries	★★★★☆
Starter	★★★★☆
Cabin lights working	No

## TYRES

### REAR LEFT TYRES

Percentage life remaining 30%

### REAR RIGHT TYRES

Percentage life remaining 30%

New/Excellent



Very good



Good



Fair



Poor

