

HAMM HD110

Description

Hamm HD+ 110 OSCILLATION, 100kW, Width of the drum 1.66m, CE, Erops cabin, Water sprinkler system, Both drum vibrating, Oscillation compaction, Moveable seat, Frequency meter, In very good and very clean condition.



Year	2011
Hours	3372
Weight	9615 kg
Serial number	H1850141
Reference	181923

[Download photos](#)



CONTACT US:
 SALES@SMITMA.COM
 +31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine power in kW	100kW,
--------------------	--------

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★★
Decals	★★★★★
Engine cover doors	★★★★☆
Chassis	★★★★☆
Steps/ladders	★★★★☆
Cabin	★★★★☆

ENGINE DETAILS AND CONDITION

Air cleaner	Clean
Anti-freeze level °C	- 31
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★★☆
Exhaust stack	★★★★☆
Hoses	★★★★☆
Good cold start	Yes
Engine power	★★★★☆
Blow by	★★★★☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆

Radiator	★★★★☆
----------	-------

SAFETY ITEMS

Seat belt	Available
Horn	Working
Parking brake	Working

OPERATOR STATION

Hourmeter	Working
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warning	No Warnings Available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★☆

FRONT DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆
Drum scrapers	★★★★☆
Travel motors	★★★★☆

REAR DRUM

Vibratory system	★★★★☆
Drum surface	★★★★☆
Rubber mounts	★★★★☆
Drum scrapers	★★★★☆
Travel motors	★★★★☆
Oil level left final drive ok	Yes
Left final drive leaking	No
Oil level right final drive ok	Yes

Right final drive leaking No

STEERING

Articulate cylinder leaking No

Play articulate cylinder ★★★★☆

Play articulating point ★★★★☆

HYDRAULICS

Hydraulic oil level ok Yes

Hydraulic lines and fittings ★★★★☆

Hydraulic tank/sight glass and cap ★★★★☆

Noise hydraulic pump normal Yes

Operating condition hydraulics ★★★★☆

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning Yes

Wiring ★★★★☆

Batteries ★★★★☆

Starter ★★★★☆

New/Excellent
★★★★★

Very good
★★★★☆

Good
★★★★☆

Fair
★★★☆☆

Poor
★★☆☆☆

